## INSPECTION REPORT REVIEW POTENTIAL HAZARDOUS WASTE SITE

	FOIENTIAL HABARDO	OS WASIE SIIE		
SITE NAME : El 1	Reno Roundhouse Area			
LOCATION : El 1			•	•
SITE NUMBER: OKD				
		: STATE FIT TA	OTHER:	
LABORATORY:	CLP EPA OTHE	R	_	11
		523	R - 9/20	5/8/
RECEIVED FROM: _	CLPEPAOTHE	DATE	RECEIVED: _	101/0191
SAMPLE TYPE(s): /	None			
SOIL	SURFACE WATER	GROUND WATER	DRINKI	IG WATER
off / on -site	SURFACE WATER off / on -site	off / on -site	off / c	on -site
CONTAMINANT(s):	Organics Inorganics	Radionuclides	Microbiolo	ogical
FOLLOW UP (Y/N):	_			
	<u>y</u> Lo	cate Drinking Wate	er Sources	
(Re)Sampling	Requested Ke	ep Site Active ("	N"=No Furthe	er Action)
Further Actio	Requested	ncur with Report	Recommendati	Lons
a high potential	erfund Site Strategy I threat to the ground ntains a recommendatio	water pathway exi	sts from an	
	Concur with Superfund nd private wells.	i recommendation.	Determine	location of

920109

